



## SKC-NS900 Geo-membrane Overlap Wedge Welder

### Garbage Imbedding Anti-filtering Welder

#### User's Guide

(SKC-NS900)

#### Notice

1. Please carefully read the literary in order to use the machine carefully.
2. Please use the three holes receptacle with earthing which capacity is more than 15A.No changing the pin at random and drag the wire to take the pin out.
3. In order to guarantee the quality of welding, please ask the people who is specialized in the line to manipulate.
4. Don't let the iron wheel be at the impress status when the machine racing.
5. Don't use the machine in a damp place for fearing the body of the machine damaged by watering.
6. The machine all were debugged before left the factory, please don't adjust at random.
7. The circuitry board in the control case carry electricity, non professional people shouldn't disassemble it at will.
8. Don't heat up for racing the body of the machine for a long time when there is no welding or the long interval of welding since the big power in this machine is great.
9. The temperature of welding isn't allowed to surpass 400°C in generally when it works normal.
10. Please heat up the machine about 30 minutes before open it when the machine don't use or be damped for a long time.
11. Without second notice if it has changed since the products in our factory consistently improve on.

#### i. Summarize

Geo-membrane welder is a new welding machine which is developed by our company. They can weld geo-membrane of various thickness and are applicable for welding of all thermal-fused material such as LDPE, PVC, HDPE, EVA, PP and PVC、HDPE、EVA、PP

The control of this series adopt PID automatic thermostatic control with high control and low temperature fluctuation. Speed control of this series adopt PWM automatic voltage and regulation speed circuit. Direct current servo the motor drive with great output torque and staple performance in walking. It can maintain a constant speed on the condition of creeping, vertical creeping and road load. Also this series of welding machine are stable in performance despite of external temperature and voltage variation.

This series of welding machine is excellent in performance and easy for operating, with high welding speed and good work quality. It is extensively used in engineering projects such as expressways, tunnels,




reservoirs, waterproof of construction and so on.

## ii. Technical Parameter

1. Output Voltage:220V      Frequency:50Hz
- 2、Power:1800W
- 3、Welding speed:0.5~5m/min
- 4 The temperature of Heating up:0~450℃
- 5、The thickness of welding material:1.0mm~3.0mm(Single membrane thickness)
- 6、Welding width:15mm×2      Interior Cavity :15mm
- 7、Welding intention≥85%Maternity material (Resistance to the direction of cutting)
- 8、Joint width:120mm
- 9 .Machine body weight:13kg

## iii. Main Components and Name




- 1.Pressure handle    2.Manipulate hand    3.Speeding knob    4.Speeding switch    5.Electric machine insurance
- 6.Temperature switch    7.power supply insurance    8.Temperature control instrument    9.Control case



## iv. Working principle

Electric machine carried with above and below pressure wheel and turn it through speed-slow box and chain steel, and heating the bracket up and turn thermal wedge to plug in between the two main materials, meantime let the pressure bracket press the pressure wheel to made the thermal-fused mother material together. The picture is as follow:



## v. Operating Criterion

**Notice:** In order to obtain the excellent quality and high efficiency, it should be manipulated by professional people since the welding quality of the machine has direct relationship with the enactment of speed and temperature.


1. The user must choose to the three holes receptacle with earthing and confirm the good connection of exterior wire. Pick the pressure handle up to separate the up and down iron wheels and then plug the power supply on.
2. Switch power supply on, and choose suitable temperature (Temperature adjusting diagram – literature) and speed,. Then pick some narrow material to weld for a try and make sure the best effect. Owing to the difference between the environmental temperature and the thickness of material, the welding temperature of the same material could be different. We can choose to a referenced speed (about 1.5m/min) when select the temperature. And then slowly adjust the temperature from low to high.(about from 250' C to 400'C)
3. The estimation of the welding temperature: it can be directly watched the transparence PE



## SKC GEOMEMBRANE WELDER

material .If the welding mark is lever-off with transparence glass status, it showed that the temperature and the speed is suitable ;if the welding mark is seriously broken up, it showed that the temperature is too high or the speed is too low; If the welding mark is not transparence with white status, it showed that the temperature is on the slow side or the speed is on the fast side .And to the non transparence material ,it also can be tested by resistance pull after the whole party is cooled down .

4. Mending the edge of the welding material smooth .The surface face to the front side, and overlap to left down and right up .The width of pulled up is 120mm.
5. Plug the welding material between the two iron wheels to make the parallel between the body of the machine and the edge of mother material, and it can weld itself after confirmed the temperature and the speed. Usually the operator just watch the warp between the welding mark and the edge of the mother material and timely rectify it within a small scope .At the end of material welding, pick up the handle to separate the up and down iron wheels.
6. Owing to the thermal inertial, it can adjust the temperature within small scope to offset the discrepancy in temperature if it comes too high or too low in the process of welding.
7. In the process of welding, it can adjust through the two interior hexangular screw on the swaying head if the welding mark is not equality in two outside. (Just the corresponding screw in the upside of intensive welding deep or in the upside of loosen welding mark shadow)
8. Welded material crossed with another material in the shape of "T". The ways of welding is as the diagram below. Cut the crossing head sticking to the thermal wedge off 12cm inclined.



## vi. The adjustment of the Pressure wheel

According to the various thickness of material, it can be adjusted the magnitude of pressure by switching the modulated screw. It will increase by clockwise, and it decrease by anticlockwise.

## vii. The Familiar Malfunction and elimination

Phenomena	Reason	The was of eliminate
NO turning of the electric machine	Non direction of power supply	Check the power supply whether it is connected or not
	The damage of Insurance wire by burning	Change the insurance wire
	The damage of speeding circuitry board lines By burning	Change the speeding circuitry board
	The damage of electric machine by burning	Change the electric machine
Non speeding of the electric machine	Speeding knob is untightly	Tight the speeding knob
	Power pipe was shocked out	Replacing the speeding wire board
Non heating up Thermal wedge	The damage of electric pipe by burning	Replacing the electric pipe
	The damage of temperature control instrument	Replacing the temperature control instrument
	Thermocouple with malfunction	Change the thermocouple
The burning of thermal wedge	The damage of temperature control instrument	Change the temperature control instrument

## viii. Maintenance

Please clean the dunghill in the thermal wedge and the mud in the chain guard and oiled the whole machine to the dry place when not using it.

**Leader Saemin International Corp.,LTD**

**Tel: 86-311-80662170**

**Email: [david@peweldingmachine.com](mailto:david@peweldingmachine.com)**

**Website: <http://www.hdpeweldingmachine.com>**



保修卡

## Maintenance book

用户信息 User information

公司名称 Company name:

地址 Add:

联系人 Contact person:

电话 Tel:

产品信息 Product information:

产品型号 Item no.:

购买日期 Purchase date:

产品序号 Product series no.: